Office of the Director General of Police Commandant General, Home Guards & Director of Civil Defence and Director General Karnataka State Fire & Emergency Services No. 1, Annaswamy Mudaliar Road Bangalore - 560 042

No.GBC(2)07/2024



Vinane : DERIJUTAN : DDATESA Kar : DDATEAD

Date: 01-07-2024

The Authorized Signatory, National Public School, No. 81, 3rd cross, 60 feet road, Dr. Vishnuvardhan main road, Banashankari 6th stage, Bengaluru - 560061.

Sir,

To.

- Sub Issue of 'Fire Advisory Certificate' to the Educational Building 'National Public School' situated at No. 81, 3rd cross, 60 feet road, Dr.Vishnuvardhan main road, Banashankari 6th stage, Bengaluru 560061.
- Ref: Your Request Letter dated 03-06-2024.

<<<<>>>>>

With reference to the subject cited above, the Regional Fire Officer, Fire Prevention 1, Bengaluru inspected the Educational Building 'National Public School' situated at No. 81, 3rd cross, 60 feet road, Dr. Vishnuvardhan main road, Banashankari 6th stage, Bengaluru 560061on 19-06-2024 with respect to fire prevention, firefighting and evacuation measures to be complied in the above premises and submitted the details as follows: -

A. Details of the building / premises: -

417124

1-age 1 tř 10

M/s. Sri Srinivasa Educational and Charitable Trust, Represented by its chairman, G.Dayanand, No. 42, 8 th Main Road, 16 th Cross, Malleshwaram, Bengaluru.	One Building.	Ground & 04 Upper floors.	<u></u>	12 Class rooms and staff room	8 Class rooms, 3 labs and 3 staff rooms	12 Class rooms and 3 staff rooms.	12 Class rooms and 3 staff rooms.	8 Class rooms, A V room and 3 staff	18.40 Mtrs.	45,627.67 Sq. mtrs		1,352.20 Sq. mtrs.	1,352.20 Sq. mtrs.	1,352.20 Sq. mtrs.	1,352.20 Sq. mtrs.	1,352.20 Sq. mtrs.	6, 761.0(23.46 mtrs. wide Dr. Vishnuvardhan	Main Road.	Vacant land belongs to applicant.	
			ЦС ЦС	• •		· ·					··						••	_				
Name and address of the Building owner	Number of buildings	Number of floors	Floor-wise details of occupancy:	Ground floor	1 st floor	2 nd floor	3 rd floor	4 th floor	Height of the Building	Site area	Built-up area of each floor: -	Ground floor	1 st floor	2 nd floor	3 rd floor	4 th floor	Total built-up area	Surrounding properties: -	East (Front)	reared of Boy	Kamate et al	Plue & Enhangering 98
03	64	05	90	1					80	60	10							12			02	Services Services Sengalur 560 042

Page 2 of 10

*

0

the Milector

	North (Side)	:	Vacant land belongs to applicant.		
	South (Side)	:	Auditorium building.		
13	Set-back area available around	th	the building: -		
	East (Front)		6.80 mtrs.		
	West (Rear)	•	6.50 mtrs.		
	North (Side)	•	6.40 mtrs.		
	South (Side)	:	8.10 mtrs.		

<u>B.</u> On inspection of this Institutional premises, the following fire prevention, firefighting and evacuation measures recommended are considered absolutely essential from fire safety point of view: -

are considered	Recommendations		
Details		(04)	
(02)	(03)	The requirement is	
Accessibility to the premises	23.46 mtrs. Mide Vishnuvardhan Main Road, located on the eastern side.	complied with	
(entronces		The requirement is complied with	
	to dovit of 6.40 mtrs. width	The requirement is	
Width of entry / exit	from 23.46 mits. while Vishnuvardhan Main Road, located on the eastern side.	complied with	
	has been provided.	Adequate.	
Diesel generators.	capacity has been provided to		
	supply and lighting, corridor staircase lighting, corridor lighting and lifts, etc, in the event of failure of electricity supply in the building.		
	Details (02) Accessibility to the premises No. of entrances Width of entry / exit Diesel	Details (02)Existing (03)Accessibility to the premisesThe Premises is abutting from 23.46 mtrs. wide Dr. Vishnuvardhan Main Road, located on the eastern side. Both the roads are hard enough to carry the weight of 45,000 kgs.No. of entrances1 entry/exit has been provided.Width of entry / exit1 entry/exit of 6.40 mtrs. width from 23.46 mtrs. wide Dr. Vishnuvardhan Main Road, located on the eastern side. has been provided.Diesel generators.One generator of 200 KVA capacity has been provided to supply alternative power for staircase lighting, corridor lighting and lifts, etc, in the event of failure of electricity supply in the building.	

ine & Emergency

agama agama e 412124

Page **3** of **10**

05	No. of staircases Available	<u>02 staircases</u> Each width of staircase: 1.50 mtrs. Width of tread: 30 cm. Height of risers: 15 cm. Nos. of riser per flight: 11 risers. Height of handrails:1.00 mtr. Head room clearance: 3.30 mtrs.	Adequate.
06	No. lifts and capacity.	1 lift of 15 passenger capacity has been provided.	The requirement is complied with
07	Fire extinguishers.	Not provided.	 Suitable portable fire extinguishers as per the requirements. a. One ABC powder extinguisher of 5 kgs. capacity & 2 fire buckets filled with clean, dry, fine sand should be provided for every 8 cars in each Basement parking area. b. One CO₂ extinguisher of 2 kgs. capacity should be provided near the entrance to each main switch board room. c. One ABC powder extinguisher of 5 kgs. capacity should be provided near the entrance to for extinguisher of 5 kgs. capacity should be provided near the entrance for extinguisher of 5 kgs. capacity should be provided near transformer, if installed. d. One ABC powder extinguisher of 5 kgs. capacity should be provided near the entrance to the generator room.

			 e. One CO₂ extinguisher of 2 kgs. capacity should be provided inside each lift room. f. One ABC powder extinguisher of 5 kgs. capacity should be kept near each staircase landing on every floor. g. Scale of suitable extinguishers for office area and food court shall be
			collected before approaching the department for final clearance, after finalizing the utilization of each area. h. All the extinguishers suggested above should be with B.I.S mark and should be located at easily accessible position without abstracting the
	Public address system	Not provided.	normal passage. Public address system with two-way communication facility shall be provided at each floor near each staircase landing with its console at the control room, located on the ground floor.
File & El Ser	ke Stute margenay Vices 10 042 * *	\mathcal{V}_{1}	Page 5 of 10

09		Not provided.	Hose reel hose of 30.00
	reel hose.		mtrs. length with drum
			and delivery hose pipes, each of 15 mtrs. length
			with gunmetal branch
			pipe shall be provided at
	6 A .		inside the hose cabinet
10	Deur		near each outlet.
10	Down comer	Not provided.	2 down comer system
	system		shall be provided near
			the staircase. Each
			system is should be of
			100 mm internal
			diameter and made of
			G.I.'C' class pipe. From
			the riser single hydrant
			outlets should be
			provided at each
11	Yard hydrants.	Networkit	landing.
	raid flydrams.	Not provided.	One number 2-way Fire
			service inlets near the entrance shall be
		· · · · · ·	provide.
12	Automatic	Not required.	Not required.
	detection and alarm system.		
13	Automatic	Not required.	Net required
	sprinkler system.	Not required.	Not required.
14	Manually	Not provide.	Manually operated
	operated	•	electrical Fire Alarm
	electronic Fire		System with call point,
	alarm system.		near each staircase
			landing at each floor and
			its control panel at ground floor shall be
			provide.
15	Underground	Not required.	Not required.
	static water		
	storage tank combined	1 of Pali	
	capacity for wet-	Canala UI FUICo e	
	riser, yard	Canonal of Police Kurnataka State File & Enargency File & Enargency Services	
		Fine Services	Page 6 of 10
	(4	Bengania REC 042	
		10 00 ×	
	an ann a' an ann ann ann ann an an an an an an an	and a local state and the set of the	

10	hydrant and sprinklers per set of pumps.		
16	Terrace tank over respective tower terrace.	The systems should be connected to an overhead tank of 60,000 litres capacity.	The requirement is complied with.
17	Pump near underground static water storage tank (fire pump with minimum pressure of 3.5 kg/cm ² at remotest location.	Not required.	Not required.
18	At the terrace tank level with minimum pressure of 3.5 kg/cm ² .	Not provide.	2 nos. booster pumps each of capable of delivering 900 liters of water per minute a 0.3n/mm2 pressure the impeller of the pump should be provided.
19	Fire control room at ground floor.	Not provide.	Fire control room should be provided at ground floor.
20	Escape routes	Not marked.	Should be marked oneach floor Th requirement is visibly t guide the employee make to safer places.
21	Fire order	Not provide.	Fire order indicating with the action to be taken be the employees in cass of fire have been displayed inside the building. The notice boards shall be writted in Kannada and Englise with telephone number of Banashankari Fire
Karnat	and state		Station i.e., 080 Page 7 of 10

			22971539 &fire Control room nos. 080- 22971600, 550, 500 & 101 telephone numbers of nearest Ambulance Services etc.
22	Firefighting training	Not trained.	40% of employees not trained in firefighting at R.A. Mundkur Fire and Emergency Services Academy. Bannerughatta road, Bangalore – 29. Hence the requirement is not complied with.

As such the Karnataka State Fire and Emergency Services department is issuing 'Fire Advisory Certificate' to the Educational Building 'National Public School' situated at No. 81, 3rd cross, 60 feet road, Dr. Vishnuvardhan main road, Banashankari 6th stage, Bengaluru 560061 from Fire prevention, Firefighting and Evacuation point of view subject to the compliance of below mentioned conditions within 03 months from the date of issue of Fire Advisory Certificate.

- 1. Recommended to provide portable fire extinguishers as per the requirements.
 - 1. One ABC powder extinguisher of 5 kgs. capacity & 2 fire buckets filled with clean, dry, fine sand should be provided for every 8 cars in each Basement parking area.
 - 2. One CO₂ extinguisher of 2 kgs. capacity should be provided near the entrance to each main switch board room.
 - 3. One ABC powder extinguisher of 5 kgs. capacity should be provided near transformer, if installed.
 - 4. One ABC powder extinguisher of 5 kgs. capacity should be provided near the entrance to the generator room.
 - 5. One CO₂ extinguisher of 2 kgs. capacity should be provided inside each lift room.
 - 6. One ABC powder extinguisher of 5 kgs. capacity should be kept near each staircase landing on every floor.

- 7. Scale of suitable extinguishers for office area and food court shall be collected before approaching the department for final clearance, after finalizing the utilization of each area.
- 8. All the extinguishers suggested above should be with B.I.S mark and should be located at easily accessible position without abstracting the normal passage.
- 2. Public address system with two-way communication facility shall be provided at each floor near each staircase landing with its console at the control room, located on the ground floor.
- 3. Hose reel hose of 30.00 mtrs. length with drum and delivery hose pipes, each of 15 mtrs. length with gunmetal branch pipe shall be provided at inside the hose cabinet near each outlet.
- 4. 2 down comer system shall be provided near the staircase. The system is should be of 100 mm internal diameter and made of G.I.'C' class pipe. From the riser single hydrant outlets should be provided at each landing.
- 5. One number 2-way Fire service inlets near the entrance shall be provide.
- 6. Manually operated electrical Fire Alarm System with call point, near each staircase landing at each floor and its control panel at ground floor shall be provide.
- 7. 2 nos. booster pumps, each of capable of delivering 900 liters of water per minute at 0.3n/mm² pressure the impeller of the pumps should be provided.
- 8. Fire control room should be provided at ground floor.


417 124

- 9. Should be marked oneach floor The requirement is visibly to guide the employees make to safer places.
- 10. Fire order indicating with the action to be taken by the employees in case of fire have been displayed inside the building. The notice boards shall be written in Kannada and English with telephone numbers of Banashankari Fire Station i.e., 080-22971539 & fire Control room nos. 080-22971600, 550, 500 & 101 telephone numbers of nearest Ambulance Services etc.
- 11. COTPA Sec-4 direction No smoking area smoking here is an offence board should be writer in English & Kannada both languages shall be prominently displayed at inside the entry /exit of each floor.
- 12. A Fire Nodal Officer shall be nominated either from teaching or non-teaching staff.

- 13. A Fire siren shall be installed in the premises to inform the students in case of a fire emergency and evacuate the area.
- 14. At least 40% of teaching & non-teaching staff should be got trained in fire prevention and firefighting evacuation measures at R.A.Mundkur Fire &Emergency Services Academy, Bannerughatta Road, Bangalore-560 029 or Regional Training centre.

Note: -

- 1. This is only the "Fire Advisory certificate" issued by the Fire Department from fire safety view of the low-rise already constructed Building. This shall not be considered as No Objection Certificate for the Building.
- 2. After completion of all the firefighting installations as advised in Fire Advisory Certificate, 'Fire Advisory Compliance Certificate' shall be obtained from the Fire and Emergency department.



Copy to Regional Fire Officer, Fire Prevention 1, Bengaluru.